

BMW 335i Maintenance Record

An anonymized service-history source for prospective readers

Vehicle described in the supplied records as a 2007 BMW 335i. The log spans roughly 162,000 km in March 2019 to 246,102 km in July 2026.

How to read this record

This document is compiled from an owner-supplied maintenance log. Registration, owner details, supplier names and locations, and dollar amounts are omitted. Dates, mileage, item names and part references are transcribed from that log; they are not independently verified and do not establish current condition or roadworthiness.

Several entries are incomplete. The 2023 camshaft sensor is listed twice; a coolant hose is dated 29 July 2025 at 246,102 km, the same mileage as an oil service dated 29 July 2026; and some 2024 parts have no individual date. Confirm these items against original receipts. A previous Marketplace listing stated 250,000 km, so confirm the current odometer before reusing that figure.

Recorded service and repair entries

Date	Odometer	Work recorded	Notes / reference
06 Mar 2019	162,000	Oil change	Routine service.
10 Oct 2019	167,000	Oil change	Routine service.
10 Oct 2019	167,000	Thermostat-to-head hose; coolant	Cooling-system service.
15 Dec 2019	-	Rear tyres	Odometer not recorded.
18 Jan 2020	170,000	Oil change	-
15 Feb 2020	172,000	Turbo wastegate repair	Note mentions header gasket and oil-feed O-rings.
22 Mar 2020	176,000	Oil cooler line	-
22 Mar 2020	176,000	Unspecified item	Source has an amount and supplier but no item description; those fields are omitted.
07 Apr 2020	175,000	Radiator top hose	-
07 Apr 2020	175,000	Front lower angle rods	Item wording retained from the source log.
07 Apr 2020	175,000	Engine mounts	-
07 Apr 2020	175,000	Oil pan gasket and bolts	-
07 Apr 2020	182,611	Turbo installation kit	-
01 Jan 2021	182,611	Oil change	-
01 Jun 2021	186,500	Oil change	-
01 Jan 2022	190,000	Rear tyres	Winrun listed in the source.
01 Jun 2022	190,000	Oil change	-
01 Jan 2023	193,927	Oil change	Penrite 5W-40.
01 Jun 2023	200,340	Oil change	Castrol 5W-40.
01 Jun 2023	205,060	Crankshaft position sensor	Part number 13627525015.
01 Jun 2023	205,060	Camshaft position sensor	Same item appears twice in the source and may be a duplicate.
01 Jun 2023	205,060	Camshaft position sensor	Duplicate entry as recorded.
15 Apr 2024	211,514	Oil and filter	5W-40 and MANN filter.
22 Apr 2024	212,000	Radiator	Mahle.
06 May 2024	215,000	Coolant expansion tank	OEM reference 17137607482; alternative references also appear in the source.
12 May 2024	215,000	Crankshaft position sensor	Part number 13627525015.

Date	Odometer	Work recorded	Notes / reference
23 Jun 2024	215,000	Camshaft position sensor	-
10 Aug 2024	216,000	Front driver's entrance strip	Wording retained from the source log.
Undated	216,000	Front and rear brake pads	Source specifies pads only.
Undated	216,000	Engine mounts	-
Undated	216,000	Front tyres	-
05 Dec 2025	227,350	Oil change	5W-40.
05 Dec 2025	-	Tyres	Winrun R330, 255/40R17; odometer not recorded.
29 Jul 2025	246,102	Coolant hose: thermostat to engine block	Date conflicts with the same mileage appearing in a July 2026 entry; verify against the original record.
21 Feb 2026	238,410	Oil change	5W-40.
29 Jul 2026	246,102	Oil change	5W-40 Nulon.

Undated or incomplete source entries

Work recorded	Source note
Coolant reservoir	No date or odometer reading.
Oil change	No date or odometer reading.
Shock absorbers and wastegate solenoid	Dates are recorded as 11 Jan 2019 and 12 Jan 2019 at 168,000 km. That mileage conflicts with later entries showing 162,000 km in March 2019 and 167,000 km in October 2019; verify the original dates/year.
Radiator entry	No date or odometer reading; source notes an insurance contribution.
Intercooler shroud clip	BMW reference 7545367; no separate date or odometer reading.
Automatic transmission fluid flush	No date, odometer reading or fluid specification.
Main drive belt service	Main drive belt, mechanical tensioner and two deflection pulleys listed at about 215,000 km; individual dates are absent.
Cooling-system parts	At about 218,000 km: water pump (11519455978), thermostat (11537549476), water-pump-to-thermostat hose (11537545665), coolant inlet hose (11537558523), and bolts. No date; the bolt reference is ambiguous in the source.
Oil service / underhood shield	An oil-change row at about 218,000 km includes underhood shield reference 51757129341; relationship between the item and reference is unclear.

For prospective buyers: compare this summary with dated invoices, confirm the current odometer and arrange an independent pre-purchase inspection. Check part fitment against the vehicle before ordering.